Oil Field Environmental Incident Summary

Responsible Party: DENBURY ONSHORE, LLC **Well Operator:** DENBURY ONSHORE, LLC

Well Name: MOSSER 2-26

Field Name: T. R. Well File #: 7668

Date Incident:2/24/2016Time Incident:11:00Facility ID Number:County:BILLINGSTwp:141Rng:101Sec:26Qtr:

Location Description: On location

Submitted By: Josh Cuppy Received By:

Contact Person: Brian Ehrmantraut

5320 LEGACY DR

PLANO, TX 75024-3127

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:2 MileDistance Nearest Water Well:2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 30 Barrels 25 Barrels 25 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/9/2016 Clean Up Concluded: 3/1/2016

Risk Evaluation:

None

Areal Extent:

All remained in treater dike.

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut in. Recover standing fluids. Remaining will be recovered by excavation of impacted soils.

Wastes Disposal Location: TR SWD and approved landfill

Agencies Involved: BLM

Updates

Date: 2/25/2016 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location within the dikes. NDIC retains oversight.